



**AEROSEAL.**

## Case Study

MEZ-AEROSEAL

# CATALINA, OFFICE CENTER

» Sealing after 10 years of building operation and reducing a total leakage by approx. 93.1% «

# CATALINA, OFFICE CENTER

**Location:** 6 WYŚCIGOWA AVENUE, WARSAW, Poland

**Date:** -

**MEZ-AEROSEAL Partner:** Energy Air Sp. z o.o

**Executing company:** -

**Result:** -



Smell



Noise



Energy  
efficiency



Air tightness



Indoor air  
quality

## Description

Warsaw office building located in Mokotów district. Construction of Catalina Office Center started in 2007 and was completed in the fourth quarter of 2009. The total area of this nine-storey office building is 22600 sqm. Sealing with AEROSEAL® technology included supply installation (7200 m<sup>3</sup>/h) responsible for staircase and staircase vestibule aeration in case of fire.

## Successful sealing

With our successful MEZ-AEROSEAL partner network we achieve great success again and again.

## The change in leakages

### Before sealing

- 694 m<sup>3</sup>/h ca.10 %

### After sealing

- 47,5 m<sup>3</sup>/h ca.0,6 %

### Reduction

- 93,10%



[www.mez-technik.com](http://www.mez-technik.com)



[info@mez-technik.de](mailto:info@mez-technik.de)



+49 (7072) 600980